


Workstation dimensions and adjustment ranges



This drawing shows the recommended dimensions and adjustment ranges for the chair, monitor, keyboard, and work surfaces. The operator in this drawing is using good posture.