NAME : TEACHERAGE - ZEBALLOS June 13, 2018

Date Produced	Work Order #	Location	Description	Employee assigned	Estimated Completion	Date Completed	Comment
01-May-16	30856	610 Keno (admin	ceiling painted	Darcy	Sep-16	Sept 2016	
			Living Room - Ceiling needs painting	Darcy	Sep-16	Sept 2016	
			Master bedroom - Ceiling needs paint	Darcy	Sep-16	Sept 2016	
			Bedroom #2 - Needs repair	Darcy		August 2016	
1-Jul-16	30859	Teach #3	Exterior needs powerwashing	Student lab		August 2016	
1-Jul-16	30860	Teach #4	Exterior needs powerwashing	Student lab		August 2016	
1-Sep-16	30861	Single wide mobi	ceiling in second bedroom	Darcy		Sept 2016	
1-Jul-16	30858	Teach #7 - 610 K	Entryway - faulty lights, screen door	Darcy	OK	Nov 2016	? Not sure what the issue is
			Kitchen - missing trim	Darcy	Oct-16	Nov 2016	trim to complete
28-Oct-16	30859	214 Pandora	Remove Gate & Fencing	Darcy	Xmas Break	Dec 2016	tear down
1-Jan-17	30860	132 Maquinna	Exit tenancy - Inspection	Romeo	Jan 31, 2017	Jan 29, 2017	all good-dam dep to be released
Jan-17	30861	610 Keno (admin	Cleaning required	Randy	03-Feb-17	Feb 2017	Custodian hired
Jul-17	30862	all Teacherages	yardwork - brush clearing	labourers	summer 2017	Complete	
30/08/2017	30863	132 Maquinna	attend to issues in email - a james	Romeo	15-Sep-17	Complete	see below furnace
Sep-17	30865	132 Maquinna	New Furnace	Romeo - HB Energ	Nov-17	cancelled	ordered
Sep-17	30866	610 A Keno	New Furnace	Romeo- HB Energy	Nov-17	cancelled	ordered
Oct-17	30867	604 Keno	New Furnace	Romeo - HB Energ	Nov-17	cancelled	
Oct-17	30868	214 Pandora	Hot water faucet leaking	Romeo	01-Nov-17	Nov 2017	
Oct-17	30869	214 Pandora	Exhaust fan stove hood not working	Romeo	01-Nov-17	Nov 2017	
Oct-17	30870	214 Pandora	Electrical outlets in kitchen - not work	Romeo	01-Nov-17	Nov 2017	
Oct-17	30871	214 Pandora	Build new fence around property	Maint	Spring/summer 2018		Cancel
Jan-18	30872	610 Keno	Rebuild Gate	Darcy	31-Jan-18	Jan 2018	fixed
Jan-18	30873	610 A Keno	Repair furnace	Romeo	09-Jan-18	Jan 2018	
07-Sep-17	30864	All Teacherages	Please take interior photos for website	Romeo/Randy	as vacated		
01-Jun-18	30900	All Teacherages	Duct cleaning	D. Mattson	Summer 2018		Contractor
06-Jun-18	30874	602 Keno	Roof leaks back porch	Romeo	Summer 2018		
01-Jun-18	30875	2 new Units	Prepare site, pour pad and hook up	Maint crew	Summer 2018		
01-Jun-18	30876	1 old unit	Prepare site, pour pad and hook up	Maint crew	Summer 2018		

5